

# Access, Inspection, Surveys & Flare-Stacks

Tall Buildings, Structures, Shafts and Flare-Stacks (Above and Below ground) require specialised access. This may be for Inspection, Alteration, or Maintenance purposes.

Due to the awkwardness or heights of the inspection works the client may not be able, or be authorised by Insurance to carry out such tasks.

Our experienced Technicians/Managers are keen to undertake these tasks liaising with the client to fulfil their requirements, eg. Carbonation, Core Drilling, reinforcement Location Tests on Concrete. Masonry Inspection checking for loose or spalling materials or misalignment, erosion and corrosion, weather damage, structural or misalignment, erosion and corrosion, weather damage, structural faults, etc.


Ultrasonic/NDT testing of materials in situ.

Materials inspection, eg. Steelwork, joints, welds, insulation and weather cladding.

CCTV and video filming or photographic surveying - including two way radio connections between camera technician and ground level monitor screen, where required.

Full written reports with photographs, etc. and if requested details of recommendations for Planned Maintenance submitted.

Clerk of Works functions have also been carried out by our qualified and experienced staff. Providing supervision of contracts inappropriate for clients own resources, thus ensuring tender specification and economic compliance.



High rise blocks of flats inspection repair



Industrial access survey chimney stack



**HEAD OFFICE:** KELLAW ROAD | DARLINGTON | CO. DURHAM DL1 4YA  
**TEL:** 01325 282794 | **FAX:** 01325 487329 | **MOB:** 07971 173626

**SOUTHERN OFFICE:** EVANS HOUSE | 107 MARSH ROAD | PINNER | MIDDX HA5 5PA | **TEL:** 0208 4296700 | **FAX:** 0208 4296755

**NEWCASTLE OFFICE:** TEL/FAX: 0191 496 1540

**E-MAIL:** ENQUIRIES@STONESERVICESUK.COM

**WEB:** WWW.STONETECHNICALGROUP.CO.UK  
WWW.STONESAFETYUK.COM

**FREEPHONE: 0800 0480 151 FAX: 0800 0480152**

