

# Steeple Maintenance


## St. James Church Carlisle

### Work Scope

**St James Church, Carlisle  
Steeple Maintenance**

**Project**

Fabric inspection, report steeple conditions.  
Removal of iron cramps to masonry, replacement masonry.  
Our craftsmen removed harmful iron cramps, which were causing stress fractures and expansion of spire masonry.  
Carefully restoration including stainless steel insert attachment.



PCC Council  
Architect  
Johnson And Wright  
01228-525161

**HEAD OFFICE:** KELLAW ROAD | DARLINGTON | CO. DURHAM DL1 4YA  
**TEL:** 01325 282794 | **FAX:** 01325 487329 | **MOB:** 07971 173626

**SOUTHERN OFFICE:** EVANS HOUSE | 107 MARSH ROAD | PINNER | MIDDX HA5 5PA | **TEL:** 0208 4296700 | **FAX:** 0208 4296755

**NEWCASTLE OFFICE:** **TEL/FAX:** 0191 496 1540

**E-MAIL:** ENQUIRIES@STONESERVICESUK.COM

**WEB:** WWW.STONETECHNICALGROUP.CO.UK  
WWW.STONESERVICESUK.COM

**FREEPHONE: 0800 0480 151 FAX: 0800 0480152**

